#### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

## WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-024418 Address: 333 Burma Road **Date Inspected:** 29-May-2011

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** XU TAO **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG** Components

### **Summary of Items Observed:**

During the fabrication of the Orthotropic Box Girder (OBG) Bike Path (BK) BK004A-031, this Quality Assurance (QA) Inspector discovered the following:

Bay#19

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member is identified as OBG Components. The weld designations reviewed are as follows:

- -(BK023A1-001-008)
- -(BK025A1-001-010)
- -(BK024A7-001-142)
- -(BK024A7-001-164)
- -(BK024A7-001-180)
- -(BK024A7-001-182)
- -(BK025A7-001-007)
- -(BK025A7-001-037)
- -(BK025A7-001-067)

Unless otherwise noted, all observed on this date appeared to generally comply with applicable contract documents.

### **Summary of Conversations:**

No relevant conversations.

# WELDING INSPECTION REPORT

(Continued Page 2 of 2)

## **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Patel, Hiranch	Quality Assurance Inspector
Reviewed By:	McClendon, Timothy	QA Reviewer